


8

FIG. 1A

Serial No. 10/722,375 Docket No. 856063.757 Inventor(s): Eusebio Di Cola et al.

c)

Express Mail No. EV529825728US "REPLACEMENT SHEET"








FIG. 3A

Serial No. 10/722,375 Docket No. 856063.757
Inventor(s): Eusebio Di Cola et al.
Express Mail No. EV529825728US "REPLACEMENT SHEET"



Serial No. 10/722,375 Docket No. 856063.757 Inventor(s): Eusebio Di Cola et al.

Express Mail No. EV529825728US "REPLACEMENT SHEET"






FIG. 3B




FIG. 4B




FIG. 5B




FIG. 6B

Serial No. 10/722,375 Docket No. 856063.757 Inventor(s): Eusebio Di Cola et al. Express Mail No. EV529825728US "REPLACEMENT SHEET"

> n_tooth_holes lock_fon i_teeth Tone wheel manager not_reset clk Control_bus 20 1/0 Interface \ Address_bus Data_bus fonica_signal Tone wheel sensor Drive shaft Tone wheel 19 missing FIG. 1C




FIG. 20

Serial No. 10/722,375 Docket No. 856063.757 Inventor(s): Eusebio Di Cola et al.

Express Mail No. EV529825728US "REPLACEMENT SHEET"




FIG. 3C







FIG. 40










F'[G: 1D

Serial No. 10/722,375 Docket No. 856063.757 Inventor(s): Eusebio Di Cola et al. Express Mail No. EV529825728US "REPLACEMENT SHEET"



Serial No. 10/722,375 Docket No. 856063.757
Inventor(s): Eusebio Di Cola et al.
Express Mail No. EV529825728US "REPLACEMENT SHEET"





F1G. 4D





FIG. 5D

Inventor(s): Eusebio Di Cola et al.
Express Mail No. EV529825728US "REPLACEMENT SHEET"






FIG. 70




FIG. 8D